405002

Certified, Filed and or Recorded on August 19, 2014 1:18 PM

BENTON COUNTY MINNESOTA MARILYN J NOVAK COUNTY RECORDER

By: BW

6 - V - I

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
North Quarter Corner of Section 30, Township 38, Range 29 4TH Principal Meridian, State of Minnesota, County of Benton At the corner location shown on the sketch: \[\text{Dn} \frac{2}{27} \frac{107}{07} \text{ found a \frac{1}{2"} \text{ PIPE LAPPED 1223b} \] \[\text{Date} \] \[\text{left monument as found } \Pi \text{ lowered monument } \Pi \text{ removed monument (explain)} \] \[\text{Dn} \frac{1}{100} \text{ placed an } \]
LOW LAND OIB OIB OID FIELD ROAD Not to scale LOW LAND DITCH SPIKE IN WOOD POST LOW LAND SPIKE IN WOOD POST LOW LAND 19 30
Statement of evidence for this corner location is on back of this page.
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.
Signature lione C. Wittstock Date 8-18-2014 License No. 19552
Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Benton County Surveyor's Office Jerome C. Wittstock, County Surveyor Minnesota License No. 19552

Statement of Evidence:

B301

North Quarter Corner of Section 30, Township 38 North, Range 29 West, Alberta Township, 4th Principal Meridian, Benton County, Minnesota.

Original US General Land Office survey set a wood post at this location and bearing trees were recorded

6" Tamarack

N 9 W

6 links

7" Tamarack

S 43 E

20 links

2002 No resurvey information was found on this corner in the Benton County records.

2007 The Benton County Surveyor's Office found a 1/2" iron pipe capped 12236 on a north-south fence line and fence east and old field road centerline west.

Coordinates Obtained by GPS NAD 83 (1996 Adjustment) N-175027.773 E-513504.377

The found iron falls on line between the northeast and northwest corners of Section 30 and 48.04 feet east of the lost position. The position fits occupation along the north-south quarter line of Section 30 with nothing that can be determined in Section 19. Since the found iron falls on line between section corners and at the intersection of occupation lines, it is accepted as marking the corner position.

E SELL STREET