

Statement of Evidence:

H362

Northeast Corner of Section 36, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1949 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

8" Elm	N 36 E	29 links
14" Blk Ash	N 54 W	20 links
12" Elm	S 74 W	29 links
14" Blk Ash	S 29 E	12 links

A line tree was noted as a 30" Elm South 21.71 chains and a 14" Poplar North 17.91 chains.

Undated Reference ties were noted to a spike

12" Basswood Stump	NE	56.2
10" Elm	NW	64.4

1901 County Surveyor's Record Book A, Map No. 42 shows a survey of Section 31, 37-28 by John E. Whilt dated March 4, 1901.

1912 County Engineer's Notebook 1, pages 37 to 42 contains a survey for SR No. 10 by M. J. Cleveland. Notes are for east-west road that intersects north-south road at possible section corner.

1938 County Engineer's Notebook 113 contains a road survey for State Road No. 4 running from east to west. Shows corner marked by a spike in 4-way road intersection. Ties:

FP	NE	55.8'
FP	NW	59.75'

1939 County Engineer's Notebook No. 131 contains survey of CAR 32 running south to north on township line. Corner is shown as a spike in center of SAR 4 with same ties as 1938.

Cor. FP	W	22.0
FP	NW	26.5

2001 Westwood Professional Services, Inc. found a PK at the intersection of the centerlines.

2008 The Benton County Surveyor's Office found a PK Nail at the four-way intersection of roads. The measurements fit well with the 1938 distances: north fits within 1.5 feet, west fits within 1 foot, south fits within 0.5 feet and east fits within 0.3 feet. Since the distances fit well and the PK is located at the four-way intersection it is accepted as marking the obliterated corner position.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-137791.774
E-542395.361

2010 The Benton County Surveyor's Office found the PK Nail and verified the 2008 coordinates.