

**Statement of Evidence:**

**J313**

The East Quarter Corner of Section 31, Township 36 North, Range 28 West, Glendorado Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
- |             |          |           |
|-------------|----------|-----------|
| 9" Bur Oak  | S 8 W    | 300 links |
| 10" Bur Oak | N 52 ½ E | 318 links |
- 1894 County Road Book, page 92, shows road surveyed by Felix Parrent, County Surveyor, east from this corner. Gives distance of 40.16 chains to the center of Section 32.
- 1914 County Road Book, pages 127 to 130, shows a survey for State Road No. 8 from the east to this corner. Notes shows "drove gas pipe in center of road".
- 1916 County Surveyor's Record Book 1, pages 67 to 69, and Record Book A, Map No. 29, contains a survey of Section 31 by J. P. Soderstrum. He states he found an iron in the center of east-west road marking the corner. His notes show he measured 40.25 chains to the NE corner and 40.26 chains to the SE corner of Section 31. However, the map gives 39.85 chains to the NE corner and 39.85 chains to the SE corner of Section 31.
- 1953 County Surveyor's Record Book 1, page 69 gives ties to iron:
- |            |     |       |
|------------|-----|-------|
| 7" W. Oak  | SSE | 68.6  |
| 10" W. Oak | ESE | 66.45 |
- 1983 David Regan, LS 12236, found a 1" solid iron pin in the center of road east-west and on fence line south. He set a cast iron monument over the iron pin and filed Certificate of Location (Doc. No. 166040). Tie distances to two Oaks SE fit close to the 1953 ties.
- 2008 Westwood Professional Services, Inc. found a 3/8" rebar flush with bituminous road surface.

County Coordinates  
NAD 83 (1996 Adjustment)  
N-103052.187  
E-547972.599