

Statement of Evidence:

The Northeast Corner of Section 6, Township 36 North, Range 28 West, Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

14" W. Oak	S 88 E	545 links
18" Bur Oak	N 82 E	510 links
6" W. Ash	N 65 W	212 links
6" Elm	S 68 W	22 links

1901 County Surveyor's Record Book 2, page 446, and Record Book A, Map No. 42, contains a survey of Section 31 by John E. Whilt. He notes a distance of 40.02 chains (2641.32 feet) to the South 1/4 corner Sec 31 and a distance of 39.39 chains (2599.74 feet) to the East 1/4 corner Sec 31.

1914 County Road Book, page 133, shows a survey for State Road No. 11 intersecting the north line of Section 5 a distance of 577 feet east of the this corner.

1915 County Surveyor's Record Book 1, pages 17 & 18, and Record Book A, Map No. 12, contains a survey of Section 5 by J.P. Soderstrum. He found no evidence of Gov't BT's, but found stump of Elm NE that checked with Whilt's BT. He set a W. Oak stake in the centerline of road and fence lines north/south with the following reference ties in links:

TP	S 71 1/2 E	111
TP	N 77 E	157
TP	S 78 W	285
TP	N 68 1/4	96 1/2
Fen Cor	N	41 1/2
Fen Cor	S	52

1939 County Engineer's Notebook No. 125 contains survey of CAR 42 running east to west on township line. No corner is shown, but notes fence south at approximate corner.

2002 Westwood Professional Services, Inc. found no evidence of a corner marker at the centerline of County Road 51 (running east and west) and an occupation line to the south. We found no evidence of the original bearing trees or of the 1915 ties. We measured from this assumed corner position 2645.57 feet to the approximate North 1/4 corner of Section 5 and measured 1475 feet south to a fence corner marking the occupied 1/16th line. These distances support the centerline of road and fence south as marking the same obliterated corner position as determined in 1915. We set a 1/2 " iron pipe and took ties and filed a Certificate of Location (#291176).

County Coordinates obtained by GPS to set iron pipe:

NAD 83 (1996 Adjustment)

N-132572.950

E-547476.058