

**Statement of Evidence:**

**J102**

The Northeast Corner of Section 10, Township 36 North, Range 28 West, Glendorado Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post with bearing trees noted as:

12" Linden	N 40 E	51 links
14" Linden	N 44 W	45 links

1902 County Surveyor's Record Book 1, page 29, and Record Book A, Map No. 41 contains a survey of Section 11 by John Whilt. He notes a distance of 39.18 chains to the North  $\frac{1}{4}$  corner Sec. 11 and a distance of 39.95 chains to the East  $\frac{1}{4}$  corner Sec. 10.

1916 County Surveyor's Record Book 1, page 13, shows survey by J.P. Soderstrum. He notes he found a stake set in centerline grade and stumps of both Gov't BT's and took the following new reference ties:

6" Maple	N 25-15 E	59 links
6" Maple	S 42-15 E	89 links
12" Maple	S 51-45 W	88 links

He notes a distance of 39.40 chains (2600.40 feet) to the East  $\frac{1}{4}$  corner Sec 3 and a distance of 40.60 chains (2679.60 feet) to the North  $\frac{1}{4}$  corner Sec 10.

County Surveyor's Record Book 1, page 27, notes an iron stake at the corner.

1930's (Undated) County Highway notes state an iron and stone at the corner with the following reference ties:

Cor FP	E	22.50
Cor FP	SW	36.90

1939 County Engineer's Notebook No. 123 contains survey of CAR 39 running south to north on section line. Corner is shown as a granite monument in center of road intersection, with roads north, south, and west and fence line east. Ties:

FP	E	22.6'
----	---	-------

1979 Paul Wellen, LS 10461, found a stone at the centerline intersection of a Twp Road and County Road 67. He set a cast iron monument and filed a Certificate of Location (#155140).

2003 Westwood Professional Services, Inc. found CIM in centerline intersection. 1979 ties are gone.

County Coordinates by GPS  
NAD 83 (1996 Adjustment)  
N - 126851.735  
E - 563561.597