

**Statement of Evidence:**

**J332**

Northeast Corner of Section 33, Township 36 North, Range 28 West, Glendorado Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

7" W Oak	S 2 E	1741 links
18" W Oak	S 1 W	1736 links

1901 County Surveyor's Record Book 1, page 61 and Record Book A, Map No. 40 is a survey of Section 27 by John Whilt, which shows this corner.

1929 County Surveyor's Book 1, page 71 and Record Book A, Map No. 49 shows a survey of Section 28 by M.B. Lang. Corner is shown, but no information given.

1933 County Engineer's notebook No. 70 shows road survey by H. G. Elletson. Corner is shown as spike in center of road intersection with roads running north and west with ties:

F.P.	East	37.7'
Pop.	N 65-00 W	74.1'
Pop.	N 45-00 W	72.7'

1935 County Engineer's Notebook No. 92 contains survey for SAR No. 7 running north to south. Notes corner as a spike with road west and fence east. Ties:

Hub	NW	43.8'	Hub	SW	37.35'
-----	----	-------	-----	----	--------

No Date County Ties to Iron Pipe:

TP	NE	41.4
TP	SE	133.5
PP	SW	44.0

1991 Dennis Taylor, LS 15233, found a RR spike set by Benton County Highway crew in 1978 at centerline of roads north, south, and west. He replaced the RR spike with a cast iron monument and filed a Certificate of Location (Doc. No. 212586).

2001 Westwood Professional Services, Inc. found a CIM in centerline of roads north, south, and west.

2005 Sam DeLeo, LS 40341, reported finding the CIM and County Coordinates obtained by GPS:  
NAD 83 (1996 Adjustment)  
N- 105663.764  
E- 558568.870

2008 The County Surveyor's Office searched and found a PK Nail over the cast iron monument set by Taylor in 1991. The Surveyor accepts the position as found and updated ties from Taylor's 1991 certificate of location.

County Coordinates obtained by GPS:  
NAD 83 (1996 Adjustment)  
N- 105663.808  
E- 558569.092