Certified, Filed and or Recorded on Nov. 04,2008 AT 01:13PM

Signed: EW

MARILYN J NOVAK G V I

BENTON COUNTY MINNESOTA

MARILYN J NOVAK

COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
NORTHEAST Corner of Section 3, Township 38, Range 30  4TH Principal Meridian, State of Minnesota, County of  At the corner location shown on the sketch:  V On 10-15-08 found a CAST IRON MONUMENT		
☐ left monument as found ☐ lowered monument ☐ removed monument (explain) ☐ □nplaced an		
YARD  58.36  PK IN PP  ORWY  GRV. RD		
YARD  60  80.56  WOODS		
Statement of evidence for this corner location is on back of this page.		
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.  Signature  Date: 1/3/08  Deputy County Surveyor  License No. 43932		
License No. 43932 PAGE / OF 2		

## Benton County Surveyor's Office Chris Hoglund, Deputy County Surveyor Minnesota License No. 43932

## **Statement of Evidence:**

C032

Northeast Corner of Section 3, Township 38 North, Range 30 West, Graham Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

Original US General Land Office set a wood post at this location and bearing 1849 trees were recorded

12" Poplar

N 40 1/2 E

397 links

Morrison County Surveyor, notes in Surveyor's Record Book A, page 58, (Morrison County) shows survey of Section 34, 39-30. Notes state found Government corner.

County Surveyor's Record Book 2, page 164, MJ Cleveland notes a hub with the 1908 following tie:

10" Blk Oak S 19 1/4 E

114 links

Phil Randall, Morrison County Surveyor, notes in County Surveyor's Record 1914 Book A, page 167, (Morrison County) a survey of Section 35, 39-30. Survey notes a stake found at the corner location and also one of the old Government witness trees.

County Engineer's Notebook No. 81 for survey of Graham aid road running south 1931 to north. Corner is shown as a hub with town road east and fence line west. Ties:

FP

NE

36.5

TP

SE 41.0

Survey terminated at this corner. (Ties also listed in Book 2, page 164)

1963 County Engineer's Notebook No. 285 contains a road survey for CR 22 running south to north on section line. Corner is shown as a spike set in center of road with town road east. Ties:

PP

NE

54.35

TP

SE 80.5

- 1990 Paul Wellen, LS 10461, found a 1" solid pin, 24" long, in the centerline of county Road 23 running south, Morrison County Road running north, and town road east. He replaced with a cast iron monument and filed a Certificate of Location (Doc. No. 199554).
- Westwood Professional Services, Inc. found a CIM at the intersection of the 2008 centerline of CR 59 north/south, centerline of township road east and a fence line west. CIM fit one remaining 1990 Wellen tie and both 1963 County Engineer's ties. CIM is accepted as marking the obliterated position for this corner location. County Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-196440.698

E-499433.513

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER  Northeast Corner of Section 3 , Township 38 N , Range 30 N , 4th P.M.		
STATE OF MINNESOTA, County of Benton		
At the corner location shown on the sketch:		
☑ On 6/7/90 found a 1" x 24" solid iron pin		
☐ left monument as found, ☐ lowered monument, ☒ removed monument (explain)		
C /7/00		
On 6/7/90 placed a Cast Iron monument		
SKETCH OF REFERENCE TIES		
45		
- N - O O O O	٠.	
WOODED	PASTURE	
THE BOXEL DEB		
To Boycepen on I d	P.P -O-	
MORRISON COUNTY 63.40 65254	MORRISON COUNTY	
BENTON COUNTY (2) 10.45	GRAVEL BENTON COUNTY	
28" OAK		
42.0	WOODED	
FARM YARD 요	/ WOODED	
000		
ENTON		
BBE	<i>f</i> .	
	• :	
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER		
contained herein was prepared by me or under County of		
(my direct supervision.	I hereby certify that this document was filed in the Co. Recorders office atM. on the	
SIGNATURE DATE	day of A.D., 19	
Registration No. 10461	County Recorder	
🛮 Land Surveyor, 🗆 Professional Engineer	By,Deputy DOCUMENT NO	
County Surveyor, Cl County Engineer	DOUGHTER INC.	

## Statement of Evidence:

Northeast corner, Section 3, Township 38 North, Range 30 West, 4th Principal Meridian.

- 1. During the G.L.O. Survey of 1849, Mr. Theodore Conkey, a U.S. Deputy Surveyor set a wood post to mark this corner.
- A search of the Benton County Surveyor and Engineer records provided no information to the location of this corner.
- 3. On January 20, 1914, Phil S. Randall, Morrison County Surveyor placed a stake at this corner.
- 4. On June 7, 1990, Paul E. Wellen & Associates, Inc. found a 1 inch solid iron pin, 24" long at the center line intersections of Benton County Road 24 to the south, Morrison County Road to the north and a gravel road to the east. We removed said iron pin and placed a cast iron monument at its location. We also established new reference ties as indicated.

BENTON COUNTY, AN CERTIFIED TO BE FILED AND YOR RECORDER AND YOR RECORDED ON SEP 27 11 31 AM 50 ALICE C. EMORLMEYER COUNTY PROORDER.