

Statement of Evidence:

A333

The East Quarter Corner of Section 33, Township 38 North, Range 28 West, Granite Ledge Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

7" Blk Ash	S 83 1/2 E	12 links
8" Elm	S 76 W	19 links

1901 County Road Book, pages 206 and 266, shows road surveyed by John Whilt, County Surveyor, running on section line. Gives distance of 80.42 chains for the east line of Section 33.

1924 County Highway plans show no corner found with distance for the east line of Section 33 measured at 5309.0 feet and road run straight between section corners.

2002 No resurvey information was found on this corner in the Benton County Surveyor's records.

2004 Westwood Professional Services, Inc. found no evidence of a corner marker. Measured 5305.26 feet between section corners. Lost position falls 5.4 feet east of the center of CSAH No. 7 and 6.4 feet north of a row of posts east and west marking occupation lines. Evidently, the road has been shifted since the 1924 alignment was run. Since there is no evidence and no record of the corner since the original survey and since the County found no evidence in 1924 and 1901 (survey gives distance for the whole mile), determined the corner to be lost. On 5/30/04 set a ½ " iron pipe with cap No. 12684 at the lost position.
County Coordinates to Lost Position

NAD 83 (1996 Adjustment)
N- 167031.012
E- 557750.479