

**Statement of Evidence:**

**A362**

The Northeast Corner of Section 36, Township 38 North, Range 28 West, Granite Ledge Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

12" Sugar	S 57 E	14 links
8" Basswood	N 58 W	17 links
10" W. Birch	N 41 E	46 links
10" Elm	S 48 W	76 links

Line trees are noted 36" Pine, South, 13.27 chains and a 8" Blk Oak, North, 15.36 chains.

1902 County Surveyor's Record Book 2, page 358 and Record Book A, Map No. 37, notes a survey of Section 25 by John Whilt. Type of monument is not shown.

No Date County Surveyor's Record Book 2, page 380, lists the following new bearing trees:

20" W. Oak stump	S 41 1/2 W	107 links
12" W. Oak stump	S 30 1/4 W	80 links

1911 Mille Lacs: "Plat of Road Survey" by Deputy County Surveyor S.L. Kennedy for a new road from the NW corner of 30-38-27 to the N 1/4 corner of 28-38-27. Said survey shows he found the NW 30 and restored the SW 30 along the County line. This survey shows a road on line on the west line of 19 and the west and the south lines of 30, but none on the west line of 31.

1921 Mille Lacs: Survey and plat of Section 30-38-27, by R.S Chapman, County Surveyor. His plat states that the subject corner was an "iron pipe and rock" set at SPM along the west line of the section, and that said west line of this section was a "Judicial Road Survey". His plat gives dimensions for all the "40s" in the section as well as angles at the corners.

1961 Benton County Highway shows an iron pipe with ties:

P.P.	SW	44.9
N end 'X' culvert	NE	51.1
S end 'X' culvert	SE	48.95

1994 John Oliver, LS 8194, Mille Lacs County Surveyor found a 2" iron pipe in the centerline-centerline intersection. He states that pipe fit line and distance extended westerly from found monuments at the S 1/4 and SE corners of Sec. 30, per Chapman's 1921 survey. They left the iron as found and placed a 1/2" iron pipe over the 2" iron pipe and filed a Certificate of Location (#244643).

County Coordinates from John Oliver & Associates by traverse

NAD 83 (1986 Adjustment)

N- 169601.971

E- 573510.294

2002 County Coordinates by GPS to Iron Pipe:

NAD 83 (1996 Adjustment)

N- 169602.462

E- 573509.706