

**Statement of Evidence:**

**L102**

The Northeast Corner of Section 10, Township 36 North, Range 30 West, Minden Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

- 1852 Original General Land Office survey established this corner and a wood post was set for the corner and bearing trees were recorded.
- |            |            |           |
|------------|------------|-----------|
| 6" Blk Oak | N 17 1/2 E | 569 links |
| 6" Blk Oak | N 67 1/2 W | 454 links |
- 1933 County Engineer's Notebook No. 71 contains survey of County road starting at this corner and running west. Notes show corner marked by a square stone with "+" in center of east-west road and fence line south. Ties:
- |    |    |       |
|----|----|-------|
| TP | SW | 26.7' |
|----|----|-------|
- 1935 County Engineer's Notebook No. 87 contains survey of SAR 3 with corner shown in 4-way road intersection. Ties:
- |    |    |       |
|----|----|-------|
| TP | SW | 34.6' |
| FP | SE | 23.0' |
- 1961 M.W. Carley ties:
- |    |    |       |
|----|----|-------|
| TP | SE | 40.18 |
| PP | NW | 40.0  |
| PP | NE | 41.16 |
- (same ties in 1968)
- 1962 County Surveyor's Record Book 1, page 179 shows an iron over a square stone with an "+" on shoulder. Ties:
- |    |    |       |
|----|----|-------|
| TP | SE | 40.05 |
| PP | NE | 41.0  |
| TP | NW | 40.0  |
| TP | SW | 39.1  |
- 1989 David Regan, LS 12236, found a 1½ " iron pipe over a stone monument in the center of road intersection. He filed Certificate of Location (Doc. No. 195019). He notes one County tie found:
- |    |    |       |
|----|----|-------|
| PP | NE | 41.14 |
|----|----|-------|
- 1995 Comstock and Davis performed GPS work under contract with Benton County and Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to a 1 ½ " iron pipe:
- N- 126697.946  
E- 500007.442
- 2008 Westwood Professional Services, Inc. placed a PK nail and county washer flush to bituminous surface over existing monument. Established reference ties.  
County Coordinates obtained by GPS  
NAD 83 (1996 Adjustment)  
N-126697.859  
E-500007.337
- 2009 The Benton County Surveyor's Office set a 1/2-inch by 14-inch iron pipe at the location of the found iron pipe.