

Benton County Surveyor's Office
 Jerome C. Wittstock, County Surveyor
 Minnesota License No. 19552

Statement of Evidence:

L292

Northeast Corner of Section 29, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey established this corner and notes show a wood post set at this location and bearing trees were recorded.

16" Bur Oak	N 61 E	1038 links
5" Bur Oak	S 12 1/2 E	433 links

1912 County Engineer's Notebook 2, pages 101 to 104, is a road survey for SR No. 8 by M. J. Cleveland. Survey was run on section lines east-west. Notes show sandstone for corner with ties:

T.P.	S 30-10 W	71.3
SE Cor. School House	N 35 W	117

1917 County Surveyor's Record Book 1, page 217, notes a sandstone at the corner with the following reference ties.

T.P.	S 30-10 W	71.3
SE Corner School House	N 35 W	117

County Surveyor's Record Book 1, pages 199-200, and Record Book A, Map No. 40, contains a survey of Section 20 by N. Drolson. Notes show that he found a stone at the intersection of roads, which according to testimony of Bossworth was set by Cronk (County Surveyor) in 1867.

1938 County Engineer's Notebook No. 110, H. G. Elletson notes PI in 4-way road intersection with ties.

T.P.	NW	54.1
Cor. F.P. NE		37.8

1970 Reference ties noted by Milner W. Carley were.

Found. Cor. School House	NW	137.25
Chiseled "X" End 22" RCP	SSW	37.19
Chiseled "X" End 22" RCP	SSW	36.35

1981 William Lunser, LS 9394, found a 1/2" iron monument at the intersection of the centerlines of County Road 8 and County Road 45, location supported by measurements south and east. On May 21, 1984 William Lunser placed a cast iron monument at the location of the 1/2" iron monument and established ties. A Certificate of Location (#191258) was recorded. The Certificate notes a distance of 2686.06 feet between the NE Corner and the N 1/4 Corner of Section 29. Tie of 137.91 feet NW to SE corner house foundation.

1992 James Nielsen, LS 11865, MN/DOT, recovered a 3/8" iron rod and three of Lunser's reference ties. The monument fits and is accepted as the correct location for the corner. A Certificate of Location (#216769) was recorded. MN/DOT Road Alignment Roll N-15 and the following road plats 05-14, 05-5, 05-6, 5-15 note a 3/8" iron rod at the corner.

County Coordinates obtained from MN/DOT
 NAD 83 (1986 Adjustment)
 N- 110717.458
 E- 489556.995

1995 Comstock and Davis performed GPS work under contract with Benton County and Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to a 1/2 " iron pipe:

N- 110717.987
 E- 489557.165

2001 Westwood Professional Services, Inc. found a 1/2" rebar at the intersection of the centerlines of County Road 8 (running north and south) and County Road 45 (running east and west). We removed the 1/2" rebar and set a cast iron monument at the location and established reference ties.

N & D, S face 30" Cottonwood, up 0.5	NW	102.19
PK NW face PP, up 1.5	SW	61.93
"x" on top Tele Ped	SE	84.39

2002 County Coordinates obtained by GPS (Cast Iron Monument)
 NAD 83 (1996 Adjustment)
 N-110718.101
 E-489556.591

2009 The Benton County Surveyor's office recovered a CIM, verified the 2002 coordinates and updated the reference ties.