

**Statement of Evidence:**

**L322**

Northeast Corner of Section 32, Township 36 North, Range 30 West, Minden Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.  
8" Bur Oak      S 75 W      74 links

1940's MN/DOT alignment map for TH 23 notes the corner is 2618.5 ft south of centerline. Pre 1940 MN/DOT notes by C. H. West, LS, for proposed TH 95 show corner assumed at centerline of road north-south and fence lines east and west.

1938 County Engineer's Notebook No. 110, H. G. Elletson lists ties to PI hub with fence west.  
T.P.      SW      26.8  
Steel F.P.      NW      29.7

1972 William Lunser, LS 9394, found a RR spike at the centerline of County Road 8 and left monument as found. A Certificate of Location (#133431) was recorded.

1992 James Nielsen, LS 11865, MN/DOT, found a RR spike at the centerline of County Road 8 and two of Mr. Lunser's ties and left the monument as found. A Certificate of Location (#216777) was recorded.  
County Coordinates obtained from MN/DOT  
NAD 83 (1986 Adjustment)  
N- 105389.070   E- 489681.934

1993 and 1994      MN/DOT Road Alignment Rolls N-15 and the following road plats 05-6, 05-5, 5-14 and 5-15 note a cast iron monument at the corner.

1995 Comstock and Davis performed GPS work under contract with Benton County and Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to a PK Nail:  
N- 105389.630   E- 489682.145

2001 Westwood Professional Services, Inc. found a PK at the centerline of County Road 8. All of previous ties are gone. We removed the PK and set a cast iron monument at the location of the PK and established reference ties  
Nail in SE face PP, up 5.0      SE      76.83  
PK in top N-end 18" Culvert      W      42.74  
PK in top S-end 18" Culvert      SW      58.17

2003 Westwood Professional Services, Inc. found a cast iron monument at the corner and located it using GPS. Filed Certificate of Location (Doc. No. 295394).  
County Coordinates Obtained by GPS (Cast Iron Monument)  
NAD 83 (1996 Adjustment)  
N-105389.749   E-489681.566

2009 Westwood Professional Services, Inc. recovered the cast iron monument, verified all reference ties from 2001 and verified coordinates from 2003.