

Benton County Surveyor's Office
Jerome C. Wittstock, County Surveyor
Minnesota License No. 19552

Statement of Evidence:

I103

East Quarter Corner of Section 6, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post was at this location and bearing trees were recorded.
- | | | |
|--------|----------|----------|
| 9" Elm | S 22 W | 16 links |
| 6" Elm | N 30 ½ E | 14 links |
- 1915 County Surveyor's Record Book 2, pages 394 and 395, and Record Book A, Map No. 17, contains a survey of Section 5 by J.P. Soderstrum. Notes show corner found and set stone.
- 1927 County Engineer's Notebook No. 80 contains survey of SAR 6 running north to south. Notes show corner marked by a hub on fence line east and west. Stationing gives distances of 2692.4 feet to the NE corner and 2627.9 feet to the SE corner with a delta angle of 2-29' right. Same ties as listed in County Surveyor's Record Book 2, page 396, which shows a hub at the corner with the following ties:
- | | | |
|------|---|--------|
| T.P. | E | 32.55' |
| F.P. | W | 30.45' |
- These ties also noted in 1956.
- 1944 County Engineer's Notebook No. 163 contains a road survey for SAR 6 running from south to north on section line. Corner is shown marked by a gr. stake in center of road with fence lines east and west. Same ties as listed in 1927. Stationing gives distances of 2631.8 feet to the SE corner and 2693.3 feet to the NE corner with a delta angle of 2-36' left.
- 1953 County Engineer's Notebook No. 196 contains a road survey for SAR 6 running from south to north on section line. Ties:
- | | | |
|---------|---|-------|
| Cor. FR | W | 30.4' |
| TP | E | 32.1' |
- Stationing same as 1944.
- 1985 Benton County Highway records indicate an iron pin at the corner.
- 1995 William Lunser, LS 9394, set a 1" iron pipe based on survey data from Ronald Engelmeyer, LS 13334. Filed Certificate of Location (Doc. No. 234177). Certificate shows distances of 2632.70 feet to the SE corner and 2693.30 feet to the NE corner with a deflection angle of 2-28-04.
- 2000 Westwood Professional Services, Inc. found iron pipe at centerline.
- 2001 Westwood Professional Services, Inc. found a ½ " iron pipe over a ¾ " iron pipe at the intersection of north-south road and tree line east-west. Replaced iron pipes with a cast iron monument. 2002 filed Certificate of Location (Doc. No. 291187).
- 2006 Benton County Surveyor's Office excavated a 10 foot by 12 foot hole down to original ground. No additional corner evidence was found. Accepted the cast iron monument as the obliterated corner. Set a ½ inch by 18 inch iron pipe capped 19552 in place of the cast iron monument. The iron pipe is 2693.12 feet from the northeast corner and 2632.94 feet from the southeast corner, which fits the distances stated in 1944 and 1995 very well.
- 2009 Benton County Surveyor's Office found a 1/2" inch iron pipe capped 19552 at the centerline of a north/south road and tree lines east/west.
County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N-161745.610
E-547379.453