

Statement of Evidence:

I092

Northeast Corner of Section 9, Township 37 North, Range 28 West, Maywood Township,
4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey established this corner and set a wood post for the corner and bearing trees were recorded.
- | | | |
|-------------|--------|----------|
| 12" Br. Oak | N 73 W | 7 links |
| 10" Br. Oak | S 59 W | 11 links |
- 1901 County Road Book, pages 206 and 266, shows road surveyed by John Whilt, County Surveyor, running north and west from this corner.
- 1915 County Surveyors Records Book 2, pages 314 and 315, and Record Book A, Map No. 9, shows J. P. Soderstrum did a survey of Section 3. The survey shows he found the stumps of 2 BT's with marks plain and shows stake set.
- 1923 County Engineer's notebook No. 33 for SR No. 7 running north-south shows a stone at the corner with stake 2 feet under. County Surveyor's Record Book 2, page 402, notes call for a stake and a stone at the corner with the same ties:
- | | | |
|----------|----|------|
| F.P. | E | 33.0 |
| Cor F.P. | NW | 32.7 |
- 2001 Westwood Professional Services, Inc. found a PK at the intersection of the centerlines of County Road 7 (running north and south) and 105th Street NE (running west). Removed the PK and set a cast iron monument at the location and established reference ties.
- 2002 County Coordinates obtained by GPS to CIM:
NAD 83 (1996 Adjustment)
N- 158959.726
E- 557833.481
- 2005 On 4/20/05 excavated corner area with Benton County Highway Dept. backhoe. Dug down 4 feet and found no evidence of the stone referred to in 1923. Soil appearance indicated that road could have been sub-cut in this area. Accepted previous set CIM position as the best evidence of the obliterated corner location.
- 2012 The Benton County Surveyor's Office found a PK Nail and replaced it with a 1/2" by 14" iron pipe capped 19552 at the accepted obliterated corner position. The 2002 coordinates were verified.