

Statement of Evidence:

I191

North Quarter Corner of Section 19, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established this corner and set a wood post and bearing trees were recorded as follows:

14" W Oak	N 39 ½ E	28 links
12" Maple	S 13 W	32 links

1915 County Surveyor's Record Book 2, pages 420 and 421, and Record Book A, Map No. 15, contain a survey by J. P. Soderstrum of Section 18. Notes he found an old tamarack post set by Sabin Peterson in same location as post set by Whilt, County Surveyor. However, Wm Milton claims the post to be a random post set by Whilt and was told so by him. Therefore he ran section line and set corner on true line. Map shows a distance of 74.82 chains between section corners and he set corner 34.84 chains (2299.44 feet) east of the southwest corner and 39.98 chains (2638.68 feet) west of the southeast corner. Made ties: 14" Br. Oak S 34 ½ W 135 links (89.1 feet) and 12" Br. Oak S 68 ½ W 43 links (28.38 feet).

1979 William Lunser, LS 9394, set ½" iron pipe at intersection of fence lines north, south, and west.

1988 William Lunser replaced iron pipe with a Cast Iron Monument. Filed Certificate No. 191269. Distances shown as 2295.16 feet to NW corner and 2640.69 feet to NE corner of Section 19. An angle of 180-09-07 to the north is given.

(NOTE: Using Soderstrum's information with Lunser's, it appears Lunser's corner is within 4 feet of line and 4 feet of distance. Lunser gives a tie of 61.46 feet southwest to a 16" Oak. Should check for Soderstrum's ties.)

2008 The County Surveyor's Office searched and found the cast iron monument as set by Lunser in 1988. Distances to the NW Cor. and the NE Cor. give 2294.77 ft. (34.77 ch.) and 2640.87 ft. (40.01 ch.), respectively, which agrees with Soderstrum's 1915 measurements. Soderstrum's bearing trees were not recovered. Ties from Soderstrum's survey were not recovered. The position falls at the intersection of a north-south and west fenceline and is also agrees with a field line to the east. The Surveyor accepts the position as marking the best evidence. Ties were updated.

County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N-148485.697
E-544707.530