

Statement of Evidence:

H352

Northeast Corner of Section 35, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

This corner is noted on the following recorded plats

THE TOWN OF FOLEY	2/23/1899	Felix Parrant
FOLEY'S 2 ND ADDITION	4/15/1902	John Abercrombie
WILDMAN & TAUER'S ADDITION	9/5/1956	Jos Kotsmith
HILLSIDE ESTATES (1/2" I.M.)	5/16/1984	Sidney Williamson

(I.M. over Stone)
Granite Mon.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

24" Elm	N 20 W	63 links
20" Linden	S 88 W	37 links

1925 County Engineer's notebook 44 lists ties:

T.P.	SW	37.5'
T.P.	NW	37.5'

1938 County Engineer's Notebook 113 contains survey for SAR 4 running east to west. Notes show corner as a granite monument in road and in line with fence north.

Ties:

TP	NW	45.1
8" Twin Cherry	SE	44.1

Stationing gives distances of 2647.6 to the NE corner and 2640.0 feet to the NW corner with a delta angle of 0-46' left.

(Notation in 1956 shows 1/2" rod placed over granite monument.)

1949 County Highway Notebook No. 1, page 64, contains notes by J. D. Kotsmith that show he found a square granite monument with + down 0.8 feet below grade with ties:

MHD in 18" Elm	NE	61.0
MHD in PP	SE	32.9
MHD-Iron	NW	37.1

1956 County Surveyor's Record Book 1, page 529, shows iron over granite monument with ties:

TP	NW	37.1 (Older)
TP	SW	37.5 (Older)
PP	SE	32.9
SE Cor Shed Found	NW	33.75

1957 County Highway Notebook 1, pages 37 and 40, contain surveys by J. D. Kotsmith that show stone monument found 761.5 feet east of stone monument in the center of Broadway from old plat of FOLEY'S 2ND ADDITION.

1965 Carlson Eng. Field Service ties:

PP	N	32.25
PP	WSW	90.58
PP	SSE	32.85
Cor Gar	NNW	33.75

1972 Kotsmith ties:

Sign Post	NW	44.7
TP	SE	46.9

1984 Sidney Williamson, LS 10918, found a large spike 1 foot south of the centerline of Broadway. He filed a Certificate of Location (168502).

1986 Bruce Skipton, LS 17768, set a $\frac{3}{4}$ " iron pipe 1.20 feet east of a found large spike. He filed a Certificate of Location (181315) stating corner was reset based on resurvey of the east line of FOLEY 2ND ADDITION and the Southeast $\frac{1}{4}$ of Section 26.

2004 MN/DOT found PK Nail, removed and did not find pipe. Set CIM.
County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N- 137588.333
E- 537111.287

2012 Benton County Surveyor's office found a cast iron monument at the same coordinates as the monument set by MN/DOT in 2004. The monument measures 2639.76 feet to the north quarter of Section 36, 2710.78 feet to the east quarter of Section 26, 2633.58 feet to the north quarter of Section 35 and 2593.57 feet to the east quarter of Section 35. The cast iron monument is accepted as the obliterated section corner.