

Statement of Evidence:

J041

North Quarter Corner of Section 4, Township 36 North, Range 28 West, Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

- 1849 Original US General Land Office survey established this corner and set a wood post at this location and bearing trees were recorded:
- | | | |
|-----------|--------|----------|
| 8" Sugar | N 30 E | 6 links |
| 12" Maple | S 53 W | 48 links |
- 1916 County Surveyor's Record Book 1, page 13, and Record Book A, Map No. 24, shows J.P. Soderstrum, County Surveyor, did a survey of Section 3. The notes show this corner was not found and he set the Northeast of Section 4 by single proportion between the NW corner of Section 4 and the North $\frac{1}{4}$ corner of Sec. 3, measuring 121.02 $\frac{1}{2}$ chains, setting the corner 40.34 chains (2662.44 feet) west of the North $\frac{1}{4}$ corner of Section 3.
- 1916 County Engineer's Notebook 1, pages 37 to 42, contains a road survey for State Road No. 10. Notes list $\frac{1}{4}$ line occupation south. Stationing gives distances of 2664 feet to the NW corner and 2689 feet to the approximate NE corner of Section 4.
- 1939 County Engineer's Notebook No. 125 contains survey of CAR 42 running east to west on township line. No corner is shown, but stationing gives distances of 2644.2 feet to the NE corner and 2673.2 feet to NW to fence line south.
- 2005 WSN found a $\frac{3}{4}$ " iron pipe in center of east-west road and in line with woods line south. Measured 2661.39 feet to the NW corner and 2657.07 feet to the NE corner. Measured 7970.61 feet from the NW corner to the apparent North $\frac{1}{4}$ corner of Section 3 as compared to Soderstrum's distance of 7987.32 feet. However, the North $\frac{1}{4}$ corner of Section 3 has not been recovered and could be 6 to 7 feet farther east. Iron pipe agrees reasonably well with Soderstrum's distance from the NW corner.
- County Coordinates obtained by GPS to $\frac{3}{4}$ " iron pipe:
NAD 83 (1996 Adjustment)
N- 132624.995
E- 555444.442