

Statement of Evidence:

J241

The North Quarter Corner of Section 24, Township 36 North, Range 28 West,
Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

24" Linn	S 19 1/2 E	26 links
12" Linn	N 65 E	16 links

1930 County Engineer's Notebook No. 58 shows road survey by H. G. Elletson running north to south. Corner is shown with ties:

F.P.	SE	38.6'
F.P.	SW	46.5'

1956 County Surveyor's Record Book 1, page 55, states there was an iron at the corner with the following reference ties.

T.P.	NW	44.55
P.P.	SE	44.45
T.P.	SE	62.00

1950's Roll E-4, of the MN/DOT Highway plans, show the corner is marked by an I. Pin and is 5415.0 feet from the North 1/4 corner Sec 25.

1965 Minnesota Department of Natural Resources found a 1/2" iron pin.

1988 William Lunser, LS 9394, found the 1/2" iron pin and replaced it with a cast iron monument and filed a Certificate of Location (#191248). Shows the NW Corner of Section 14 is 2649.08 feet west of this corner. He notes on Certificate of Location (#191249) the distance between the NE Corner and this corner is 2619.75 feet.

2002 Westwood Professional Services, Inc. found a Broken CIM and obtained coordinates by GPS.

County Coordinates
NAD 83 (1996 Adjustment)
N-116381.410
E-571587.070