

**Statement of Evidence:**

**J291**

The North Quarter Corner of Section 29, Township 36 North, Range 28 West,  
Glendorado Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.  
18" Blk Oak                      N 41 E                      297 links
- 1901 County Road Book, pages 209 and 265, shows road surveyed by John Whilt, County Surveyor, running from NW corner Section 30, 36-29 to east of the North 1/4 corner Section 29, 36-28 on section lines.
- 1914 County Road Book, page 133 shows a survey for State Road No. 11 intersecting the north line of Section 29 a distance of 814 feet east of the North 1/4 corner.
- 1925 County Engineer's notebook No. 46 shows road run from the NW corner to the NE corner of Section 29. No 1/4 corner is noted.
- 1942 MN/DOT notes (B89, P1-34) call for corner at centerline of east-west road and fence lines north-south.
- 1948 Roll O-11, of the MN/DOT Highway plans, show the corner is at the centerline of a road east/west and a fence line north/south.
- 1949 MN/DOT plans show road moved south of 1942 location.
- 1997 MN/DOT found no evidence of the corner.
- 1999 MN/DOT set a cast iron monument for the corner at the 1942 position and filed a Certificate of Location (No. 261579).
- 2000 MN/DOT filed another certificate for omission to one tie tree. (No. 264148).
- 2003 Westwood Professional Services, Inc. found a CIM:  
County Coordinates obtained by GPS to CIM  
NAD 83 (1996 Adjustment)  
N- 110947.429  
E- 550700.129