

Statement of Evidence:

J321

The North Quarter Corner of Section 32, Township 36 North, Range 28 West, Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

6" Blk Oak	S 84 E	330 links
6" Blk Oak	S 9 1/4 W	680 links

1894 County Road Book, page 92, shows road surveyed by Felix Parrent, County Surveyor, south and east from this corner. Gives distances of 40.16 chains to the center of Section 32 and 40.13 chains to the NE corner of Section 32.

1914 County Road Book, page 133 shows a survey for State Road No. 11 running north and south on 1/4 lines from this corner. Stationing shows a distance of 5266 feet from the South 1/4 corner of Section 32.

1914 County Road Book, pages 127 to 130, shows a survey for State Road No. 8 from the east at this corner. Notes show "drove gas pipe in center of road north-south". Gives distance of 2694 feet to the NE corner of Section 32.

1924 County Engineer's Notebook No. 37 shows survey of SR No. 6 from the south to this corner being 5259.6 feet north of the South 1/4 corner. Ties

Cor. F.P.	SE	39.3'
Hub	NE	40'

1929 County Engineer's Notebook No. 62 shows road survey by H. G. Elletson starting at this corner and running east. Corner is shown in center of road intersection with roads running north, south, and east with ties:

T.P.	W	30.0'
Cor. F.P.	SE	39.3'

Stationing gives distance of 2647.7 feet to the NE corner.

1930 County Engineer's notebook No. 79 shows iron pin at the corner with tie:

F. P.	SE	39.3'
-------	----	-------

Measured 2636.0 feet to the NW corner.

1953 County Surveyor's Record Book 1, page 71 has ties to an iron:

Fen Cor	SE	39.3
Hub	NE	40.0

Other ties:

PP	SW	47.5
Fen Cor	SE	67.0

2008 Westwood Professional Services found a 1/2" iron pipe cap No. 16095 (Dennis Pederson).

County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N- 105642.814
E- 550659.706