

Statement of Evidence:

J361

The North Quarter Corner of Section 36, Township 36 North, Range 28 West,
Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
8" Black Oak S 68 1/2 W 13 links

1930 County Engineer's Notebook No. 58 shows road survey by H. G. Elletson running north to south. Corner is shown with ties same as listed in County Surveyor's Record Book 1, page 57 and page 79, which notes a hub at the corner with the following reference ties:
T.P. SE 76.2
F.P. E 34.8

1965 County Engineer's Notebook No. 254 contains survey for SAR No. 9 running south to north. Notes corner as a spike set. Ties:
PP SW 49.25'
TP SE 70.8'

1979 On November 16, 1979, John Oliver, LS 8194, found a 3/8" iron rod (which fits various described parcels in the "Village of Glendorado"). He removed the iron and placed a cast iron monument at the location and filed a Certificate of Location (#155687).

2001 On August 28, 2001 Westwood Professional Services, Inc. found a RR Spike flush in the centerline of County road and dug under the spike by hand and found a spike with ribbon down 1 foot. Position was accepted as the same location as the CIM set by Oliver.

2002 Westwood Professional Services, Inc. obtained coordinates on the found spike prior to highway reconstruction. On 11/5/02 a 1/2 " iron pipe was set at location of the found spike after road construction.

2008 The Benton County Surveyor's Office found Gary Stevenson's iron monument (RLS #12684) as set in 2002, and accepts his method and position as the quarter corner between Sections 25 and 36. Ties were updated from John Oliver's 1979 Certificate of Location.

Benton County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N-105638.364
E-571773.576