

**Statement of Evidence:**

**J142**

The Northeast Corner of Section 14, Township 36 North, Range 28 West, Glendorado Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

12" Ash	N 46 E	39 links
18" Ash	N 31 1/2 W	44 links

1901 County Surveyor's Record Book 1, page 29, and Record Book A, Map No. 41, contains a survey by John E. Whilt of Section 11, which shows this corner.

1930 County Engineer's Notebook No. 58 shows road survey by H. G. Elletson running north to south. Corner is shown as a nail with ties:

T.P.	SE	41.2'
Birch		41.7'

Newer Ties:

T.P.	SE	40.7'
Birch		48.9'

County Surveyor's Record Book 1, pages 29, states there is an iron at the corner with the following reference ties.

T.P.	SE	40.7
Birch	SW	48.9

1965 Minnesota Department of Natural Resources' survey crew notes that this corner was set per County Records at the intersection of two roads.

1988 William Lunser, LS 9394, found a large spike at the intersection of two roads. He replaced the large spike with a Benton County cast iron monument and filed a Certificate of Location (#191246). Lunser notes a distance of 2669.40 feet to the East 1/4 corner of Section 14.

2001 Westwood Professional Services, Inc. found a cast iron monument at the intersection of the centerlines of County Road 9 (running north and south) and 35<sup>th</sup> Street NE (running east and west). Prior to road reconstruction, we dug under the cast iron monument down to original ground. We found a 1" X 18" iron with a pinched bottom down 3.5 feet below the surface with a large amount of wood around it.

2002 On 11/5/02 set a 1/2 " iron pipe after road construction at CIM location.  
County Coordinates obtained by GPS (CIM)  
NAD 83 (1996 Adjustment)  
N-121628.970  
E-568856.172