

**Statement of Evidence:**

**J242**

The Northeast Corner of Section 24, Township 36 North, Range 28 West, Glendorado Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

6" Tamarack	N 24 E	21 links
6" Tamarack	S 32 E	2 links
6" Tamarack	S 17 W	18 links
6" Tamarack	N 30 W	15 links

Line trees were noted as a 12" Basswood South 20.15 chains and a 6" Elm North 16.85 chains.

1965 Minnesota DNR survey notes show corner at the intersection of an old fence line north, south, and east and the centerline of an old road to the west.

1988 William Lunser, LS 9394, found corner fence post broken off. He dug and found remaining part of corner post and replaced with a Cast Iron Monument. He filed a Certificate of Location (Doc. No. 191249).

1996 County Coordinates from John Oliver & Associates by traverse:  
NAD 83 (1986 Adjustment)  
N- 116498.589  
E- 574203.570

2002 No resurvey information was found on this corner in the Benton County Surveyor's records and Mille Lacs County records have not been checked.

2008 The Benton County Surveyor's Office searched and found a cast iron monument at the approximate P.I. location of an old east-west, north-south path. Position fits Lunser's ties from 1988. Surveyor accepts Lunser's evidence and updated ties.

County Coordinates  
NAD 83 (1996 Adjustment)  
N-116499.031  
E-574204.204