Certified, Filed and or Recorded on Nov. 04,2008 AT 12:37PM

Signed: BU MARILYN J NOVAK G V I BENTON COUNTY MINNESOTA MARILYN J NOVAK

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTHEAST Corner of Section Z6, Township 38, Range 30  4TH Principal Meridian, State of Minnesota, County of  At the corner location shown on the sketch:  On 10-22-08 found a CASTIRON MONUMENT	
☐ Inplaced an	
WOUDS/YARD #1 23 24 26 25 1 30.27 FIELD 23 24 26 25	
WOODS 64.21/ SPK ENDIN 15"W.OAK  FIELD  5636	
Statement of evidence for this corner location is on back of this page.	
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.  Signature	

## Benton County Surveyor's Office Chris Hoglund, Deputy County Surveyor Minnesota License No. 43932

## **Statement of Evidence:**

C262

Northeast Corner of Section 26, Township 38 North, Range 30 West, Graham Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

12" Aspen

N 76 E

27 links

10" Aspen

S 67 W

8 links

1944 County Engineer's Notebook No. 164 contains a road survey for CAR 25 running south to north on section line. Corner is shown marked by a hub set in center of road with town road east and west. Ties same as listed below in 1949.

1949 H. G. Elletson, County Engineer, notes the following reference ties to a hub:

12" W Oak

NW

95.9

12" W Oak

SW

82.1

1961 County Surveyor's Record Book 2, page 208, notes the following reference ties to an iron:

PP

SE

70.0

Cor FP

SW

47.2

(Notation in Notebook No. 164 shows iron set.)

1983 David Regan, LS 12236, found a 1" Solid Pin over a wood stake in the centerline of roads north/south/east/west. He replaced it with a cast iron monument and filed a Certificate of Location (#166050).

2002 Westwood Professional Services, Inc. found a CIM.

County Coordinates Obtained by GPS to CIM:

NAD 83 (1996 Adjustment)

N-175064.929

E-505597.747

Westwood Professional Services, Inc. found a CIM at the intersection of roads north/south/east/west fitting 1983 Regan ties. CIM is accepted as marking the obliterated position for this corner. Coordinates obtained by GPS coincide with 2002 position.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER  Northeast Corner of Section 26		
DATE		
SKETCH OF REFERENCE TIES		
FENCE R.R. THE POST ROST ROST ROST ROST ROST ROST ROST R		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.    August   1/4/83	OFFICE OF THE RECISTER OF DEEDS  County of	