

East Quarter Corner of Section 29, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded
14" Bur Oak N 28 E 647 links

This corner is noted on the following recorded plats

BRENNAN'S ADDITION 8/28/1951 M.B. Lang
CERTIFICATE OF SURVEY FOR A.J. RUDOLPH 7/14/1988 Bruce Skipton

1938 County Engineer's Notebook No. 110 contains survey of north-south, but no corner is mentioned.

1947 Roll O-09, of the MN/DOT Highway plans, File No. 30-39 and S.P. 0503, show the corner is at the intersection of roads east/west/south/north. It also notes a distance of 62.4 feet south to the centerline.

1972 William Lunser, LS 9394, found a RR spike in the bituminous, which was substantiated by a RR spike at the 1/16 on the East line of the SE1/4. He filed a Certificate of Location (#133430) and notes a distance of 2619.95 feet to the SE corner Sec 29 and a distance of 62 feet to the centerline of MN TH23.

1984 Doc. No. 191258, by William Lunser notes a distance of 2709.42 feet to the NE corner Sec 29.

1992 James Nielsen, LS 11865, found a cast iron monument and all of Lunser's ties. He filed a Certificate of Location (#216768)
County Coordinates obtained from MN/DOT
NAD 83 (1986 Adjustment)
N- 108008.806
E- 489624.201

1993 and 1994 MN/DOT Road Alignment Roll N-15 and the following road plats 05-4, 05-5, 5-6, 5-7, 5-14, 5-15 note a Benton County CIM at the corner.

2007 CIM was not found. Westwood positioned the corner from information on Right of Way Plat 5-15. Overall mile fit shown information.

County Coordinates as derived from Right of Way information
NAD 83 (1996 Adjustment)
N-108009.483
E-489623.831

2008 Westwood Professional Services, Inc. found a PK nail. Established reference ties to corner and verified 2007 coordinates.