

**Statement of Evidence:**

**L303**

East Quarter Corner of Section 30, Township 36 North, Range 30 West, Minden Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded:  
4" Bur Oak N 86 E 53 links  
5" Bur Oak N 21 W 89 links

This corner is noted on the following recorded plats:

<i>MARCHRIS THIRD ADDITION</i>	5/30/1995	David P. Regan	CIM
<i>MARCHRIS FOURTH ADDITION</i>	5/10/1996	David P. Regan	

No Date County Surveyor's Record Book 1, page 219, refers to an iron at the corner with the following reference tie.  
Fen. Corner S 29

1922 Highway Department notes indicate a monument at the corner, but do not reference the monument to the highway centerline.

1937 County Engineer's Notebook No. 98, Elletson notes the following ties to a spike.  
F.P. S 30.4  
P.P. SW 37.05

1940's MN/DOT Highway plans for TH 23 show a field stone at the corner, which is at the intersection of roads east/west and a fence line north/south and a distance of 789.5 feet south to the centerline. Older MN/DOT Highway plans shows a distance of 772.8 ft to centerline.

1947 Highway Department calls for a field stone at the corner 789.5 feet north of TH23 station 103+89.50.

1973 William Lunser, LS 9394, found an iron pipe and left it as found and established reference ties. A Certificate of Location (#134366) was recorded.

1978 Paul Wellen's, LS 10461, records note a distance of 5441.76 feet to the West 1/4 corner Sec 30.

1992 Paul Wellen found a 1/2" iron at the intersection of County Road 46 (running east and west) and a fence line form the north and south. Replaced the iron with a cast iron monument. A Certificate of Location (#216291) was recorded.

1992 James Nielsen, LS 11865, found a cast iron monument per Paul Wellen's ties. He determined that the position of the CIM agrees with the 1947 information. A Certificate of Location (#216773) was filed.  
County Coordinates obtained from MN/DOT  
NAD 83 (1986 Adjustment)  
N- 108078.259  
E- 484257.602

1993&94 MN/DOT Road Alignment and Road R/W Plats No. 05-4, 05-5, 5-15 notes a Benton County CIM at the corner.

2001 Westwood Professional Services, Inc. found a cast iron monument at centerline-centerline.  
County Coordinates obtained by GPS  
NAD 83 (1996 Adjustment)  
N-108078.755  
E-484257.325

2008 Westwood Professional Services, Inc. placed a pk nail and county washer over existing CIM, established reference ties and verified the 2001 coordinates.