

Benton County Surveyor's Office
Jerome C. Wittstock, County Surveyor
Minnesota License No. 19552

Statement of Evidence:

L132

Northeast Corner of Section 13, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original General Land Office survey established this corner and a wood post was set for the corner and bearing trees were recorded.

4" Blk. Oak	N 84 E	174 links
2" Blk. Oak	N 37 W	156 links

Undated Roll O-10, of the MN/DOT Highway plans for S.P.0503, File No. 34-94, note a hub at the corner and shows a distance of 1102.4 feet north to the centerline and a distance of 2665.2 feet north to the East ¼ corner Sec 12. It also notes the following reference ties

FP	E	32.9	FP	NE	46.6
----	---	------	----	----	------

Roll O-11, of the MN/DOT Highway plans for S.P.0503, File No. 10-11, note a distance of 1086.0 feet to the centerline.

1930 County Engineer's Notebook No. 60 and County Surveyor's Record Book 1, page 185, notes a hub at the corner.

F.P. 3 rd	NE	46.6	Cor F.P. E	32.9
----------------------	----	------	------------	------

Notes show fence line east.

Undated notes call the corner with the following reference ties.

F.P.	E	32.7	F.P.	NE	48.5
------	---	------	------	----	------

1995 Comstock and Davis, Inc. placed a 1/2" iron pipe capped RLS #16097 at the intersection of the centerline of County Road 25 and a fence line from the east and established reference ties. A Certificate of Location (#230319) was recorded.

Comstock and Davis performed GPS work under contract with Benton County and Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to an iron pipe:

N- 121465.278

E- 510689.415

2001 Westwood Professional Services, Inc. found a 1/2" iron pipe at the centerline of County Road 25 and fence line from the east. Removed iron pipe and set a cast iron monument at the location and established new reference ties.

N & D "MHD SRP" in 24" Cottonwood	SW	142.45
Spike in 5" Double W Oak	E	47.39
Spike in 4" Ash	SE	70.40

William Lunser notes a distance of 2674.76 feet to the East ¼ corner Sec. 13 per

Doc. No. 283120, which checked well.

County Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-121465.430

E-510688.950

2004 MN/DOT survey crew found CIM.

County Coordinates furnished by MN/DOT

NAD 83 (1996 Adjustment)

N-121465.411

E-510688.861

2008 Westwood Professional Services, Inc. found a CIM. The monument falls in the centerline of the north-south bituminous road and on the gravel road west. Coordinates were checked and reference ties were recorded.