Certified, Filed and or Recorded on Nov. 06,2008 AT 08:49AM

Signed:

MARILYN J NOVAK G V T
BENTON COUNTY MINNESOTA

MARILYN J NOVAK

COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
EAST QUARTER Corner of Section 22, Township 37N, Range 28W
At the corner location shown on the sketch: On 10/20/08 found a 3/4" IRON PLEE CAP # 17259 Town 0.2'
☐ Interpolation ☐ Interpolati
FIELD TREES & 2223)
SET SPIKE MIZ" ASH CATTAILS 66.39
TREES SET SPIKE IN 8" ASH TREES
Statement of evidence for this corner location is on back of this page.
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.
Signature

Benton County Surveyor's Office Jason W. Oberg, Deputy County Surveyor Minnesota License No. 45872

Statement of Evidence:

I223

East Quarter Corner of Section 22, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

12" Elm

N 29 ½ E

116 links

6" Poplar

S 63 ½ E

31 links

1915 County Surveyor's Record Book 2, pages 430 and 431, and Record Book A, Map No. 3, shows a survey of Section 23 by J. P. Soderstrum. Notes show he found old stake at 40.22 chains north of the SW corner, which was used as the corner for road survey. He notes fence west at 40.29 chains north of the SW corner of Sec. 23. According to the map, he did not use either position, but set the ¼ corner lost at 40.18 chains north of the SW corner of Sec. 23.

The County Surveyor's Office searched and found a ¾" capped iron pipe (#17259) approximately 0.2' below the surface of the centerline of a north-south gravel road (175th Avenue N.E.). Distance to the NE corner of Section 22 measures 2649.93 ft. (40.15 ch.). Distance to the SW corner of Section 23 measures 2649.56 ft. (40.14 ch.) which checks well with Soderstrum's 1915 lost position and distance of 40.18 ch. to said SW corner of Section 23. Surveyor accepts the position as marking the Corner and updated ties.

County Coordinates to ³/₄" iron pipe NAD 83 (1996 Adjustment) N-145701.203 E-563294.975