

Statement of Evidence:

I113

East Quarter Corner of Section 11, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey established this corner and set a wood post for the corner and bearing trees were recorded.
8" B. Ash S 48 1/2 W 37 links
12" Lind S 24 E 18 links
- 1902 County Surveyor's Record Book 2, page 406 and Record Book A, Map No. 31, contains a survey by John E. Whilt of Section 11. He shows a distance of 40.30 chains (2659.8 feet) to the NE corner of Section 11.
- 1937 County Engineer's Notebook No. 82 contains a road survey for SAR No. 9 running north to south. Notes show corner marked by a hub with fence lines east and west. Ties:
8" Elm SE 115.8'
FP NE 35.8'
FP E 34.4'
Stationing gives distances of 2652.8 feet to the NE corner and 424.1 feet to the center of TH 23.
- 1951 Roll B-12, of the MN/DOT Highway plans for S.P.0504 (TH23=23), dated November 9, 1951, show the following distances:
701.7 feet east to the centerline
378.5 feet south to the centerline
2670.6 feet to the SE corner Sec 11
- 1960 County Surveyor's Record Book 2, page 406, shows a hub was found and replaced with an iron with the following ties.
NW School Foundation SE 95.85
T.P. SE 37.5
16" Elm SE 115.9
- 1961 County Engineer's Notebook No. 234 contains survey for CSAH 9 running south to north on section line. Notes show corner marked by an iron in center of road with same ties as above in 1960. Stationing gives distances of 2668.7 feet to the SE corner.
- 1962 County Engineer's Notebook No. 269 contains a road survey for SAR No. 9 running south to north. Notes show corner marked by a found hub and placed iron with fence line west. Same ties as in 1960. Notes a new tie in 1972 as: Sign Post NE 24.05'.
Stationing gives distances of 2652.6 feet to the NE corner and 377.75 feet to the center of TH 23.
- 2001 On October 16, 2001 Westwood Professional Services, Inc. found a spike in bit at the intersection of the centerline of County Road 9 (running north and south) and an occupation line from the east. Also found 1" solid iron pin below it along with the remains of a hub. Removed both and set cast iron monument and established reference ties.
- 2003 CIM was found to be 377.61 feet north of the centerline of TH 23 and 2668.08 feet north of the Southeast corner of Section 11. Measured 2652.44 feet to the NE corner of Section 11. Corner accepted as marking the obliterated position.
County Coordinates by GPS
NAD 83 (1996 Adjustment)
N- 156505.329
E- 568395.028