

Statement of Evidence:

I333

East Quarter Corner of Section 33, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
- | | | |
|----------|--------|----------|
| 12" Lind | S 27 W | 24 links |
| 10" Lind | N 65 E | 44 links |
- 2000 Bogart, Pederson & Associates set a RR spike at the centerline of a County Road and a tree line from the west. Measured 2561.74 feet to the NE corner and 2585.50 feet to the SE corner of Section 33. They considered the corner set at the obliterated position.
- 2001 Westwood Professional Services, Inc. found a RR spike at the intersection of the centerline of a County Road (running north and south) and a tree line from the west. Removed the RR spike and set a cast iron monument at the iron location.
- 2002 No information was found on this corner in the Benton County records.
- 2003 County Coordinates computed from traverse information furnished by Surveying & Engineering Professionals, Inc.
NAD 83 (1996 Adjustment)
N- 135231.851
E- 558095.827
- 2011 The Benton County Surveyor's Office found the cast iron monument in the center of the North-South road with a tree line west with a distance of 2561.61 feet to the Northeast corner and 2585.37 feet to the Southeast corner. The cast iron monument is accepted as marking the obliterated corner position.