Certified, Filed and or Recorded on Oct. 31,2008 AT 08:23AM

Signed: MARILYN J NOVAK 6 V J BENTON COUNTY MINNESOTA MARILYN J NOVAK COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Northeast Corner of Section 2D, Township 38, Range 31 4TH Principal Meridian, State of Minnesota, County of At the corner location shown on the sketch: On 8-25-08 found a CAST IRON MON.		
☐ left monument as found ☐ lowered monument ☐ removed monument (explain) ☐ □nplaced an		
FIELD TOP & TBX 46.26 TOP & TBX 73.45 FIELD WOODS FIELD		
Statement of evidence for this corner location is on back of this page.		
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.		
Signature		

Benton County Surveyor's Office Chris Hoglund, Deputy County Surveyor Minnesota License No. 43932

Statement of Evidence:

D202

Northeast Corner of Section 20, Township 38 North, Range 31 West, East Langola Township, 4th Principal Meridian, Benton County, Minnesota.

- Original US General Land Office survey set a wood post in a mound with pit 8 links east at the corner location.
- 1916 County Surveyor's Record Book 2, page 82, and Record Book A, Map No. 28, contains a survey of Section 16 by J.P. Soderstrum, which notes he set corner by testimony where pieces of old stake had been found, which is 18" east of east edge of a wagon track. Testimony of resident that road to the west was OK at time of previous survey. Ties:

TP SE 97.0 links (64.02') TP NE 141.8 links (93.59')

1929 County Engineer's Notebook No. 54 contains road survey for CAR A (21) run north from SAR No. 12. Ties to hub at corner:

TP NE 95.3' TP SE 65.0'

- William Lunser, LS 9394, found a 1/2" iron pipe at the centerline of roads south/west. He filed a Certificate of Location (#133441). Distances given: 2674.79 feet to the North ¼ corner of Section 20 and 2664.63 feet to the East ¼ corner of Section 20.
- 1983 William Lunser set a cast iron monument at the location of the 1/2" iron pipe in the centerline of roads south/west. He filed a Certificate of Location (#173415).
- 2004 MN/DOT
 County Coordinates obtained by GPS
 NAD 83 (1996 Adjustment)
 N-180224.859
 E-457171.682
- Westwood Professional Services, Inc. found a CIM at the corner location. CIM falls at the intersection of roads north/south/west. Distances to the N1/4 and E1/4 of Section 20 fit 1971 Lunser ties. CIM is accepted as marking the obliterated corner location. County coordinates obtained by GPS verify 2004 MN/DOT coordinates.

38.31

Minn. Registration No. 9394

Revised 5-17-1983

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

	e 15 day of March , 19 71
	cheast corner of Section 20,
Twp. 38, Rg. 31, Benton	County, Minnesota, which
was evidenced by $a^{\frac{1}{2}}$ iron p	pipe found inplace
I funthon centify that in order	er to perpetuate said corner I di
-	lace a permanent marker consisting
	nton County Cast Iron Mon and that
I did establish witness or refer	rance monuments as shown below:
•	
	1
	·
•	·
	4" Pine 96.21
#P 46.86	
210.27	
$N_{\frac{1}{4}}^{\frac{1}{4}}$ Cor. Sec. 20 σ^{-} $\sqrt{\frac{-2674.79}{5.75}}$	NE. Cor. Sec. 20
Sec. 20 6 C-1 Pd	½" I. Pipe
C-H Md.	C. I. M.
	C-L Co. Rd. 21
, • -	
2664	
	i
,	VE Cor. Sec. 20 173415
	beg cor. Sec. 20 170410
I hereby certify that the	Office of the Register of Deeds
above is true and correct	Benton County, Minn
and that I am a registered Land Surveyor under the laws	I hereby certify that the withi
of the State of Minnesota.	instrument was filed for record in this office on the 16th day of
holida del	ma 1005 of 110

Alice C Engelmeyer Register of Deeds

Deputy.

By.

Langala

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

