

Statement of Evidence:

H293

East Quarter Corner of Section 29, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as:

10" Ash	N 31 W	22 links
18" Bur Oak	S 84 E	20 links

1949 County Highway Engineer's Notebook No. 169 contains road survey for CAR 37 running from south to north on the section line. Corner is shown marked by a hub set in the center of road with fence line west. Ties:

16" Elm	SW	48.0
18" Stump	SW	69.4

Stationing gives distances of 2638.3 feet to the SE corner and 2627.8 feet to the NE corner with corner being a POT.

1983 David Regan, LS 12236, found a 1/2" pipe in the centerline of roads north/south and a fence line west. He filed a Certificate of Location (#167984).

2003 Westwood Professional Services, Inc. found 1/2" iron pipe that checked with 1983 ties on certificate. Also noted an Elm stump SW at 48 feet that fit 1941 highway tie. Measured 2640.92 feet to the SE corner and 2627.00 feet to the NE corner.

2008 The County Surveyor's Office searched and found a 1/2" iron pipe at approximately 3" west of the centerline of north-south road (County Road No. 61). Position agrees with the 1949 distances to the NE and SE corners (2627.0 ft. & 2640.9 ft. vs. 2627.8 ft. & 2638.3 ft, respectively). The Surveyor accepts the position of the iron and set a PK nail over the iron pipe with a Benton County Surveyor disk flush with the road surface and updated ties.

County Coordinates Obtained by GPS to 1/2" iron pipe
NAD 83 (1996 Adjustment)
N- 140373.114
E- 521226.191