

**Statement of Evidence:**

**H101**

North Quarter Corner of Section 10, Township 37 North, Range 29 West, Gilmanton Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

4" Linden	S 33 /12 E	20 links
8" Linden	S 80 E	21 links

1942 MN/DOT alignment map for TH 25 shows corner assumed in center of east-west road and in line with fences north-south. Corner is 131.1 feet west and 109.0 south of the centerline of TH 25 with a distance of 2650.2 feet given to the NE corner of Section 10.

2002 No resurvey information was found on this corner in the Benton County records.

2009 The County Surveyor's office found an iron capped 12236 at the corner of fences south and west. The distance east to the northeast corner measures 2.5 feet short of the 1942 MnDOT distance and 14 feet long of the distance to the centerline of TH 25 east and 11 feet long of the distance north to the centerline of TH 25.

County Coordinates Obtained by GPS to found iron pipe capped 12236

NAD 83 (1996 Adjustment)

N-158938.836

E-529392.363

2012 The Benton County Surveyor's Office reviewed the corner location and accepted the found iron pipe capped 12236 as the best available evidence of the corner location. The 1942 MnDOT location may have been about 11 or 12 feet north of the found iron pipe, but without physical evidence to contradict the current monumented location, there is not enough evidence to move from the found iron pipe location.