

Statement of Evidence:

H191

North Quarter Corner of Section 19, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

13" Linden	N 27 1/2 W	10 links
14" Blk Oak	S 51 1/2 E	17 links

1939 County Engineer's Notebook No. 158 contains road survey for CAR No. 20 running east to west along the section line. Corner is shown as a spike set in center of road with fences north and south. Ties:

FP	N	21.5'
FP	NE	26.25'

Stationing gives distances of 2648.2 feet to the NE corner and 2616.7 feet to the NW corner with a delta angle of 0-32' left.

1979 Paul Wellen, LS 10461, found a 3/4" iron pipe in center of east-west road and power line north-south. He set a cast iron monument and filed a Certificate of Location (Doc. No. 160208). His notes give a measurement of 2618.70 feet to the NW corner of Section 19.

2008 The County Surveyor's Office searched and found Wellen's 1979 cast iron monument along centerline of an east-west gravel road (County Road 43). Position gives a distance to the NW Cor. of 2618.59 ft. and a deflection (east to west) of 0°23'36"-left, which agrees with 1939 measurements. Thus, the cast iron monument is accepted as marking the best evidence. Ties were updated.

County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-148209.559
E-513418.786