

Statement of Evidence:

H221

North Quarter Corner of Section 22, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

12" W Birch	S 12 ½ E	15 links
10" Sugar	N 24 ½ W	36 links

1939 County Engineer's Notebook No. 158 contains road survey for CAR No. 20 running east to west along the section line. Corner is shown as a spike set in center of road with fences north and south. Ties:

FP	N	24.1'
FP	NW	28.2'

Stationing gives distances of 2639.7 feet to the NE corner and 2679.1 feet to the NW corner with a delta angle of 0-55' left.

1948 MN/DOT alignment plans for TH 218 (TH 25) shows assumed corner 2587.0 feet west of the centerline and 2641.3 feet west of the NE corner of Section 22.

2001 Westwood Professional Services, Inc. found a PK at centerline east-west and occupation north-south.

2002 No resurvey information was found on this corner in the Benton County Surveyor's records.

2004 PK Nail was found to be 2582.0 feet west of the centerline of TH 25 and 2682.89 feet east of the NW corner of Section 22.

County Coordinates Obtained by GPS to PK Nail:

NAD 83 (1996 Adjustment)

N- 148297.353

E- 529339.253