

Statement of Evidence:

H291

North Quarter Corner of Section 29, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post with bearing trees noted as:

12" Blk Ash	S 3 W	18 links
15" Elm	N 8 1/2 W	22 links

2002 No record information found on this corner since original survey in the Benton County records.

2003 Westwood Professional Services, Inc. established obliterated corner position in center of east-west road and in line with fence line south. This position fell 7.25 feet north of a straight line between section corners and 9.3 feet east of the midpoint. Set 1/2" iron pipe.

County Coordinates Computed
NAD 83 (1996 Adjustment)
N- 142990.598
E- 518638.420

2009 The Benton County Surveyor's Office set a 1/2" by 14" iron pipe capped 19552 at the obliterated corner position established in 2003

2012 Benton County Surveyor's Office found a 1/2" iron pipe capped 19552 in the centerline of an east/west road. The coordinates of the found pipe match the coordinates of the pipe set by Westwood in 2003. The position measures 2654.15 feet to the NE corner and 2672.80 feet to the NW corner of Section 29. The found iron is accepted as the obliterated Quarter corner.