

Statement of Evidence:

H062

Northeast Corner of Section 6, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

12" Elm	N 67 3/4 E	144 links
12" Elm	N 27 W	47 links
16" Elm	S 60 W	9 links

2002 No record evidence was found on this corner in the Benton County Surveyor records.

2003 Westwood Professional Services, Inc. found a 3/8" iron rebar in center of east-west road.

County Coordinates Obtained by GPS to iron:

NAD 83 (1996 Adjustment)

N- 164308.417

E- 516360.827

2011 The Benton County Surveyor's Office found the rebar and drove a 1/2-inch by 14-inch iron pipe over the top of the rebar. The rebar falls in the east-west centerline of County Road 84, fitting proportionate locations at the north quarter corners of Section 5 and 6 within 1.5 feet. The rebar is accepted as the best available evidence of the corner location. The 2003 coordinates were verified.