

Statement of Evidence:

H082

Northeast Corner of Section 8, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

10" Blk Ash	N 23 W	38 links
8" Blk Ash	S 13 E	34 links

1949 County Highway Engineer's Notebook No. 169 contains road survey for CAR 37 running from south to north on the section line. Corner is shown marked by a wood stake and an iron in the center of road with fence lines east and west. Ties are the same as listed below.

1949 County Surveyor's Record Book 1, on page 475 lists ties to a stake and iron:

20" Elm	West	30.7
24" Ash	NE	89.4
Cor. FP	East	31.4

1961 County Highway Department lists same ties as 1949.

2001 William Lunser, LS 9394, found a PK nail in center of north-south road and in line with fence line east. He accepted the nail as marking the obliterated corner position and set a ½ " iron pipe. He filed Certificate of Location (Doc. No. 283110). Certificate lists distances:

2627.76 feet to the North ¼ corner of Sec. 8
2627.10 feet to the North ¼ corner of Sec. 9
2687.70 feet to the East ¼ corner of Sec. 5
2624.50 feet to the East ¼ corner of Sec. 8

2009 The Benton County Surveyor's Office found a 1/2-inch iron pipe capped 9394 in the north-south centerline of County Road 61 on a fence east. The corner measures 2624.81 feet south (found stones at the east quarter of Section 8) and 2686.34 feet north (CIM reset after determining northeast corner of Section 5). The remainder of distances from 2001 compare within 0.1 feet. The found iron falls at the intersection of occupation lines described in 1949 and measures within a foot of the 1949 distances south. The 1/2-inch iron pipe capped 9394 is accepted as marking the obliterated corner position.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-158847.333
E-521568.798