

Statement of Evidence:

J103

The East Quarter Corner of Section 10, Township 36 North, Range 28 West, Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post with bearing trees noted as:

6" Ash	S 29 1/2 W	12 links
10" W Birch	N 15 3/4 W	13 links

1902 County Surveyor's Record Book 1, page 29, and Record Book A, Map No. 41 contains a survey of Section 11 by John Whilt. He notes a distances of 39.95 chains (2636.7 feet) to the NE and SE corners. (Indicates that corner could have been set lost.)

1939 County Engineer's Notebook No. 123 contains survey of CAR 39 running south to north on section line. Corner is shown as an iron in center of road with fence line east. Ties:

14" W. Oak	NW	49.75'
14" Elm	NE	96.95'

Stationing gives distances of 2636.1 feet to the SE corner and 2640.4 feet to the NE corner with delta angle of 1-30' right.

2007 Sam DeLeo, LS 40341, found a wood post and cast iron hitch +/-5 feet west of the road centerline. The location of the post measured 2636.43 feet to the SE corner and 2640.86 feet to the NE corner with a deflection of 1°31' right. These measurements match closely with the measurements recorded in 1902 and 1939. A 1/2" diameter iron pipe with cap "DELEO 40341" was set over the wood post.

2008 The Benton County Surveyor's Office searched and found a 1/2" iron pipe capped "RLS 40341" as set by Samuel Deleo. Location gives 2640.84 ft. to the NE Cor. of Sec. 10 and 2636.43 ft. to the SE Cor. of Sec. 10, with a deflection of 1°31'20" right. This agrees very close to the 1939 survey and is accepted as the best evidence.

Benton County Coordinates obtained by GPS

NAD 83 (1996 Adjustment)

N-124210.988

E-563539.160

Benton County Surveyor's Office
Jason W. Oberg, Deputy County Surveyor
Minnesota License No. 45872

2/18/2003

1/5/2018