

Statement of Evidence:

East Quarter Corner of Section 16, Township 36 North, Range 28 West, Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

10" Elm	N 43 1/2 E	21 links
6" Ash	S 87 1/2 W	4 links

1935 County Engineer's Notebook No. 92 contains survey for SAR No. 7 running north to south. Notes corner as a hub set in center of road. Ties:

12" Bass. Stp.	SE	48.4'
14" Ash	NW	59.3'
12" Maple	SW	54.8'

Stationing gives distances of 2437.6 feet to the NE corner and 2767.2 feet to the SE corner with a delta angle of 0-05' left.
(NOTE: This position seems out of place-probably not the corner, but a PI.)

1960 County Engineer's Notebook No. 227 contains survey for SAR No. 7 running south to north. Notes corner as an iron pipe in center of road with field entrance west. Ties are the same as below in 1961. Stationing gives distances of 2668.5 feet to the SE corner and 2539.0 feet to the NE corner with a delta angle of 0-05' right.

1961 County Surveyor's Record Book 1, page 39, gives County Highway ties to an iron on centerline with field entrance west and being north of fence line:

16" Ash	NW	59.3
15" Maple	SW	54.8

2005 WSN found a 3/4" iron pipe in center of north-south road, 12 feet north of fence line east and in line with driveway west. Measured 2668.90 feet to the SE corner and 2539.50 feet to the NE corner. Accepted pipe as marking the obliterated corner position.
County Coordinates obtained by GPS:
NAD 83 (1996 Adjustment)
N- 119000.083
E- 558377.538