

**Statement of Evidence:**

**E023**

The East Quarter Corner of Section 2, Township 38 North, Range 32 West, West Langola Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

- 1852 Original US General Land Office surveyor, Edwin James, Jr., set a wood post at this location and bearing trees were recorded.
- |             |        |           |
|-------------|--------|-----------|
| 8" Bur Oak  | N 55 E | 175 links |
| 12" Bur Oak | S 11 W | 367 links |
- 1977 On June 23, 1977 William Lunser, LS 9394, set a 1/2" iron pipe at the intersection of the centerline of a road along the NE1/4 and a fence line along the 1/4 section line of Sections 1 & 2. He filed a Certificate of Location (#147082). The iron is 3.3 feet south of an east/west fence line.  
This corner is 2644.15 feet south of the NE Corner of Sec 2.  
This corner is 2673.50 feet north of the SE Corner of Sec 2.
- 1978 On February 28, 1978 Paul Wellen, LS 10461, found a 3/4" iron pipe at the corner location, which was 3' south of a fence line running east and west. He filed a Certificate of Location (#151878).
- 1979 On July 10, 1979 Paul Wellen noted that a distance shown on Document No. 147082 was incorrect. The distance reads 2644.15 feet and it should instead read 2653.50 feet.
- 1989 On November 20, 1989 William Lunser set a cast iron monument using existing ties and filed a Certificate of Location (#195967). He shows a distance of 2653.50 feet to the NE corner of Section 2.
- 2002 On January 24, 2002 Westwood Professional Services, Inc. found a Highway Department Cast Iron Monument at the corner location.  
County Coordinates by GPS  
NAD 83 (1996 Adjustment)  
N- 193517.349  
E- 440600.870
- 2008 Westwood Professional Services, Inc. found a CIM at this location. Measures 2653.62 feet the NE corner of Section 2 and 2668.32 feet to the SE corner of section 2. CIM is accepted as marking the obliterated corner position.  
Observation by GPS confirms 2002 coordinates.