

Statement of Evidence:

A323

East Quarter Corner of Section 32, Township 38 North, Range 28 West, Granite Ledge Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

6" Elm	S 5 W	192 links
5" Willow	N 29 W	56 links

1930 County Engineer's notebook No. 56 contains a road survey by H. G. Elletson for CAR No. 27. Notes show road survey run south to north along section line. Corner is shown as a spike at south end of bridge. Stationing gives distances of 2596.6 feet to the SE corner and 2620.7 feet to the NE corner of Section 32 with a deflection angle of 0-15 right.

1958 County Surveyor's Record Book 2, page 372, notes corner exactly at Bridge.

2004 Measured 5219.78 feet between section corners. Searched area of bridge, but found no evidence of a corner marker. Corner should be reset using 1930 information.

2006 After excavation at the northeast corner of Section 5, Township 37 North, Range 28 West, this corner was positioned using the 1930 information between said northeast corner and the northeast corner of Section 32, Township 38 North, Range 28 West. A $\frac{1}{2}$ " by 15" iron pipe with a cap marked "19552" was set at this position.

County Coordinates
NAD 83 (1996 Adjustment)
N- 167023.961
E- 552502.246