

Statement of Evidence:

A111

North Quarter Corner of Section 11, Township 38 North, Range 28 West, Granite Ledge Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

16" Bur Oak	S 1 E	25 links
8" Sugar	N 46 E	16 links

1901 County Road Book, pages 206 and 266, shows road surveyed by John Whilt, County Surveyor, running north and east from this corner.

1967 County Engineer's Notebook No. 267 contains survey of CSAH 22 running west to east on section line. Corner is shown as an iron in center of road in line with fence lines north and south. Ties:

PP	S	56.5'
12" Elm	NW	91.15'
20' Elm	NW	81.75'
12" Oak	S	96.75'

Stationing gives distances of 2644.1 feet to the NW corner and 2645.7 feet to the NE corner with deflection angle of 0-05' right.
(County Surveyor's Record Book 2, page 330, shows same ties.)

1973 William Lunser, LS 9394, set a 1/2 " iron pipe at the intersection of road east-west and fences north-south and filed Certificate of Location (Doc. No. 137341). Notes that position is supported by measurements of 2643.85 feet to the NW corner and 2646.73 feet to the NE corner of Section 11.

2005 WSN found a rebar in east-west road. Measured 2643.60 feet to the NW corner and 2647.00 feet to the NE corner.
County Coordinates obtained by GPS:
NAD 83 (1996 Adjustment)
N- 190723.201
E- 565221.935

2008 Westwood Professional Services, Inc. found a 3/8" rebar in the centerline of C.S.A.H No. 22 and in line with fences north and south. Field crew found two of the 1967 County Engineer's ties with fit the rebar well. Rebar is accepted as marking the obliterated position for this corner. Coordinates for the rebar and distances to the NW and NE section corners both obtained by GPS coincide with 2005 WSN information.