

**Statement of Evidence:**

The East Quarter Corner of Section 1, Township 36 North, Range 30 West, Minden Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at the corner location and bearing trees were recorded.

4" Blk Oak	S 58 1/2 E	67 links
4" Blk Oak	N 29 W	42 links

A line tree was noted as an 18" Blk Oak East 23.24 chains.

1930 County Engineer's notebook No. 60 for CR 25 running north-south does not indicate a corner and gives a distance of 5344.4 feet for the east line of Section 1.

1959 County Engineer's Notebook No. 208 contains a survey for CSAH No. 25 running south to north on the section lines. No corner is shown, but a fence line east is noted at 2649.0 feet from the SE corner and 2689.1 feet from the NE corner.

2002 No record evidence has been found for this corner since the original GLO survey in the Benton County Surveyor's records.

2003 Barry Doridan, LS No. 23044, set a PK nail for this corner on a straight line between section corners at the intersection of the westerly projection of a fence line in Section 6 from the East Quarter corner of Section 6, T36-R29. He measured 2682.78 feet to the NE corner and 2654.87 feet to the SE corner. The corner is 13.9 feet south of the lost position. Certificate of Location filed as Document No. 295385.  
County Coordinates furnished by B & H.  
NAD 83 (1996 Adjustment)  
N- 129436.275  
E- 510600.710

2004 MN/DOT found PK Nail and replaced with CIM.  
County Coordinates obtained by GPS.  
NAD 83 (1996 Adjustment)  
N- 129436.068  
E- 510599.587

2010 The Benton County Surveyor's Office found a PK Nail, not CIM, and all ties checked.