

Statement of Evidence:

L063

The East Quarter Corner of Section 6, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

- 1852 Original US General Land Office survey set a wood post and bearing trees were recorded.
- | | | |
|------------|------------|----------|
| 6" Blk Oak | N 53 3/4 E | 42 links |
| 6" Blk Oak | N 77 1/2 W | 66 links |
- 1917 County Records contain a survey subdividing Section 6 by R.H. West, which notes a stake at this corner. The survey gives a distance of 2821 feet to the NE Cor Sec 6 and a distance of 2686 feet to the SE Cor Sec 6. (This appears to be at the lost position.)
- 2006 Bogart, Pederson and Associates performed a survey in Section 5. A spike was found in the north-south centerline on a fence to the west. The spike was replaced with a 1/2-inch iron pipe with cap 12236.
- 2007 Westwood Professional Services, Inc. found a 1/2" iron pipe capped 12236 in the north-south centerline of gravel road on a fence to the west. The found iron pipe measures 2830 feet to the northeast corner of Section 6 and 2679 to the southeast corner of Section 6. These measurements differ from Mr. West's distances being 9 feet long to the north and 7 feet short to the south with the overall mile measuring within 2 feet of the 1917 distance. The corner should be excavated 8 feet south looking for the stake to the south.

County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N-129339.995
E-483977.492

- 2010 The Benton County Surveyor's Office excavated a 8-foot by 12-foot hole, centered 8 feet south of the found iron pipe, to below original soil depth. No additional corner evidence was found. The found iron pipe is accepted as marking the obliterated corner position.
- 2011 The Benton County Surveyor's Office found the 1/2" iron pipe, established reference ties as shown and verified the 2007 coordinate position.