

Statement of Evidence:

L103

East Quarter Corner of Section 10, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post was set at this location and bearing trees were recorded.

6" Blk Oak	S 60 W	104 links
6" Blk Oak	S 28 1/4 E	170 links

1961 M. W. Carley ties:

PP	NE	34.8
TP	NW	56.8

1982 David Regan, LS 12236, found a 3/4 " iron pipe in center of north-south road and replaced pipe with a Benton County cast iron monument. Filed Certificate of Location (Doc. No. 162591)

2005 Certificate of Survey by William Lunser, LS 9394, shows the corner being 2682.30 feet north of the SW corner of Section 11.

2007 Westwood Professional Services, Inc. found a 1/2" open iron pipe in the centerline of a north-south road. New reference ties were created. The iron fits Mr. Lunser's distance to the south within 0.1 feet and fits a split of the distance between section corners within approximately 0.5 feet. A fence line to the east at the north sixteenth fits a split within approximately 5 feet of a split. I accepted the 1/2" iron pipe as marking the corner position.

County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N-124014.484
E-500034.589