

Statement of Evidence:

L113

The East Quarter Corner of Section 11, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original General Land Office survey established this corner and a wood post was set for the corner and bearing trees were recorded.

12" Tamarack	S 38 E	28 links
6" Tamarack	N 50 1/2 E	15 links

2002 Research of County records found no information on this corner.

2004 MnDot found steel fence post.

County Coordinates obtained by GPS
NAD 83 (1996 adjustment)
N – 123857.252
E – 505336.96

2009 Westwood Professional Services, Inc. found a steel post sticking 2-feet above water level in a wetland. A distance of 2669.82 feet was measured to the NE corner of Section 11 and a distance of 2653.00 feet was measured to the SE corner of Section 11. The post position is on a fence line running east-west and agrees with north-south occupation about $\frac{1}{4}$ mile to the north. The post was accepted as marking the East Quarter corner of Section 11 and reference ties were established.

County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N-123857.311
E-505337.019