

Statement of Evidence:

L193

The East Quarter Corner of Section 19, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original U.S. General Land Office survey established this corner and a wood post was set for the corner and bearing trees were recorded.
6" Blk Oak N 1/2 W 1090 links

1917 County Surveyor's Record Book 1, page 199, and Record Book A, Map No. 44 shows survey of Section 20 done by N. Drolson. He notes he set a post in a swamp along a fence line from the SE corner of Section 19 and at a distance of 40.01 chains from the NE and SE Corners Sec 19. he notes a ditch runs east.

1931 County Surveyor's Record Book 1, page 197, shows a post under a rock, 1 foot west of the fence corner and notes a distance of 2640 feet to the SE Corner Sec. 19.

1995 Kevin Festler, LS 22702, found a 1/2" iron pipe on east side of fence corner with fence lines running west, north, and south. He filed a Certificate of Location (#230323).

2003 County Coordinates obtained by GPS to 1/2 " Iron Pipe.
NAD 83 (1996 Adjustment)
N- 113420.723
E- 484172.346
Found pipe to be 2643.67 feet north of the SE corner of Section 19.

2008 Westwood Professional Services, Inc. found a 1/2" open iron pipe at a fence line to the west. Distances fit 1917 and 1931 distances within 3 feet. Established reference ties to the corner and verified the 2003 coordinates.