

**Statement of Evidence:**

**G203**

East Quarter Corner of Section 20, Township 37 North, Range 30 West, 4<sup>th</sup> Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

3" Blk Oak	S 32 W	125 links
3" Blk Oak	S 1/2 E	75 links

2002 No resurvey information was found on this corner in the Benton County records.

2006 Westwood Professional Services, Inc. set a ½ inch iron pipe capped RLS 19552 at the intersection of the centerline of the road to the east and a line between the northeast and southeast corners of Section 20 as the best available evidence to mark the obliterated position. The position fits GLO distance south within 0.24 feet and north within 0.24 with an apparent 2-pole bust.

Coordinates Obtained by GPS  
NAD 83 (1996 Adjustment)  
N-145442.190  
E-489536.178