

Statement of Evidence:

L111

The North Quarter Corner of Section 11, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post and bearing trees were recorded.

24" Bur Oak	S 7 1/2 W	67 links
10" Bur Oak	N 26 3/4 W	100 links

No Date County Surveyor's Record Book 1, page 181, notes a hub at the corner with ties:

FP	NW	32.4	FP	SW	26.0
FP	NW	32.5	TP	N	17.0

2009 Westwood Professional Services, Inc. found a 12 inch spike on the E/W centerline and fence extension to the north. The spike was determined to be strong evidence supporting the obliterated location and falls on line between the northwest and northeast corners of Section 11. It was replaced with a ½ inch iron pipe marked RLS 19552.

County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N-126612.919
E-502645.677